

HONDA ACCORD
1998 & LATER WITH BAXA/MAXA TRANSMISSION

DELAY IN REVERSE AND 1-2 BIND-UP
HARSH DRIVE ENGAGEMENT




Figure 2




Figure 3