



ZF INDUSTRIES

VALVE BODY RECONDITIONING KITS

ZF Industries has made available to the aftermarket, original equipment valve body reconditioning kits. These kits include new valve springs, orifice plugs, small parts, including checkballs and any other valve updates that have been made. Currently there are only two kits available, they are for the ZF5HP-18 and ZF5HP-30. The part numbers for these are listed under "Service Information" below.

CORRECTION:

Contrary to belief, there is no valve body reconditioning kit available for the ZF5HP19. There has never been one available, nor will there be any time soon.

The valve body reconditioning kit for the ZF5HP24 was recalled to correct various problems and as of August 12, 2005, has not yet been re-released, however, it should be available soon. The part number for the ZF5HP24 kit is listed under "Service Information" below and can be used when the kit has once again been made available.

SERVICE INFORMATION:

ZF5HP-18 VALVE BODY RECONDITIONING KIT.....	5HP18VBK
ZF5HP-30 VALVE BODY RECONDITIONING KIT.....	5HP30VBK
ZF5HP-24 VALVE BODY RECONDITIONING KIT.....	5HP24VBK

(Note: This kit covers BMW, Jaguar and Rover applications.)

PLEASE REPLACE PAGE 116 IN THE ATSG 2005 BLUE SEMINAR MANUAL WITH THIS CORRECTED PAGE.